



Service Bulletin #002 [Click HERE for PDF version](#)

PRODUCT SAFETY RECALL STRIKE FIRST CORPORATION OF AMERICA SERVICE BULLETIN #002

- About Strike First
- Fire Extinguishers
- Extinguisher Cabinets
- Submittal Sheets
- Site Map

TO: FIRE EQUIPMENT DEALERS & INSPECTION, SERVICE AND RECHARGE ORGANIZATIONS

SUBJECT: Strike First 2.5 lb and 5 lb Dry Chemical Fire Extinguishers • Models WBSF-ABC110AP, WBSF-ABC210AP and WBSF-ABC340AP • Certain serial numbers only (see below)


DATE: December 2005

Strike First retrofit program

Strike First Corporation of America ("Strike First") is issuing Service Bulletin #002 as a supplement to Service Bulletin #001 issued in August 2004. Strike First has determined that the valve stem seat in a number of its 2.5 and 5 lb fire extinguishers assembled between December 2002 and February 2004 may prevent the extinguisher from discharging properly when the lever is activated. As a result of this condition, Strike First has initiated a fire extinguisher retro-fit program for these units. **RETRO-FIT KITS ARE AVAILABLE FREE OF CHARGE BY CONTACTING YOUR LOCAL STRIKE FIRST DISTRIBUTOR, OR BY CONTACTING STRIKE FIRST DIRECTLY.**

How to identify affected units

Only Strike First models WBSF-ABC110AP, WBSF-ABC210AP and WBSF-ABC340AP with the following serial numbers are subject to this Notice.



<u>Model number</u>	<u>Affected serial numbers</u>
WBSF-ABC110AP	TC101566-TC108819
WBSF-ABC210AP	TC114969-TC135000 VV822001-VV832000 WH161001-WH167622
WBSF-ABC340AP	TC135894-TC142345

These units are designed for commercial, industrial, multi-residential and vehicle applications. The vast majority will be found in businesses and other commercial spaces, which require service by a fire extinguisher service company. To locate the serial number, look at the label of the fire extinguisher, below the "UL" mark, as depicted in the following photographs:

WBSF-ABC110AP

WBSF-ABC210AP

WBSF-ABC340AP



How does the retrofit program work?

Strike First is making available, free of charge, retrofit kits for retrofitting the fire extinguishers that are affected by this Bulletin. Each retrofit kit includes a replacement valve stem assembly, and detailed instructions for removing the existing valve stem assembly from an affected unit and replacing it with the new valve stem assembly. Once the valve stem assembly in an affected unit is properly replaced by a qualified fire extinguisher service organization, the unit will discharge as intended.

Dealers: Strike First asks that you contact persons and organizations to whom you sold the limited class of fire extinguishers affected by this Bulletin, and provide them with a copy of the attached "Notice to Owner", which describes the retrofit program and advises the owner how to ensure that the unit is properly retrofitted. In the event that you sold fire extinguishers affected by this Bulletin to another distributor or dealer, Strike First asks that you forward a copy of this Bulletin and a copy of the "Notice to Owner" to that distributor or dealer.

Inspection, service and recharge organizations: Strike First asks that: (a) you contact persons and

organizations that are known to possess fire extinguishers affected by this Bulletin, and provide them with a copy of the attached "Notice to Owner", which describes the retrofit program and advises the owner of an affected unit how to ensure the unit is properly retrofitted; and (b) in the course of inspecting, servicing and recharging fire extinguishers affected by this Bulletin, or as requested by an owner, you retrofit affected units in accordance with the instructions and using retrofit kits provided by Strike First.

Contacting Strike First

For further information, or to obtain retro-fit kits and instructions on how to retro-fit your Strike First fire extinguisher, contact your local Strike First distributor, or contact Strike First directly: Strike First Corporation of America, 1330 Progress Drive, Front Royal, Virginia, 22630. Telephone: 1-800-255-5515. Fax: 1-800-822-5001. Email: info@strikefirstusa.com Website: www.strikefirstusa.com



Corporate Office
1330 Progress Drive
Front Royal, Virginia 22630

540 636-4444 Tel
540 636-4455 Fax
800 255-5515 Toll Free Tel
800 822-5001 Toll Free Fax

Western Distribution Center
4058 S. McCarran Blvd. • Bldg. A
Reno, Nevada 89502

[About](#) :: [Hose Storage Cabinets](#) :: [Submittal Sheets](#) :: [Site Map](#)
[Fire Extinguisher](#) - [Choosing the Right Extinguisher](#) :: [ABC Dry Chemical Fire Extinguisher](#) :: [CO2](#) :: [Class K](#) :: [Brackets](#) :: [Parts](#) :: [MSD Sheets](#)
[Extinguisher Cabinets](#) - [Cabinet Guide](#) :: [ADA Requirements](#) :: [Architectural Specifications PDF](#) :: [Architectural Cabinet Overview](#)
[Specialty Cabinets](#) :: [Apex Series](#) :: [Safeguard Series](#)
[Find A Dealer](#) :: [Warranty](#) :: [Catalog Request](#) :: [News & Events](#) :: [Newsletter](#) :: [Contact Us](#)
